Tuesday, 11/14/2006 10:08:40 AM Date: User: Kim Johnston **Process Sheet** : STEP WELDMENT **Drawing Name** Customer : CU-DAR001 Dart Helicopters Services Job Number : 29412 : 12577 **Estimate Number** : D3562042 **Part Number** P.O. Number D3562 REV A : 11/14/2006 S.O. No. : **Drawing Number** This Issue : N/A : NC Project Number Prsht Rev. : LARGE FAB ASSY : A : // Type **Drawing Revision** First Issue : 29412 Material **Previous Run** : 11/24/2006 **Due Date** 5 Um: Each Written By Checked & Approved By JLM : Est Rev:A Comment **Additional Product** Job Number: Seq. #: **Machine Or Operation:** Description: 1.0 D2622120C Extrusion 5.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Qty Part# Description Extrusion 3282/5 1 D2622-120C Check Material for any Dents or Defects 2.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Cut D2622 extrusion to 15 to 15 to 15 as per Dwg D3562 2-Deburr and bevel ends for welding 3.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 4.0 D2734 206 Step Endplate Comment: Qty.: 2.0000 Each(s)/Unit Total: 10.0000 Each(s) Pick: Qty Part Number Description Batch End Cap 329340 2 D2734


Dart Aerospace Ltd

W/O:		WORK ORDER CH	WORK ORDER CHANGES					
DATE STEP		PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			V.					
	<u></u>							

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
·			QA: N/C C	losed:	Date:

NCR:			WORK ORDI	ER NON-CONFORMANO	CE (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
			*					
		-0					-1	
				4				

NOTE: Date & initial all entries




Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
07-01-02	5.0 11b.	guid end plate flush	FF.	07-01-10	5	asim	07.01.02		
	,								

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C (Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B	3	Verification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto	
				8.4					
							1		
							3		

NOTE: Date & initial all entries



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector		
) h	Ç		
				•					
		-							
		14.							


Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:	
ωψ ₁		•	QA: N/C (Closed:	Date:	

NCR: WORK ORDER NON-CONFORMANCE (NCR)							4	
		Description of NC		Corrective Action Section B		Verification		Approval
DATE S	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto
21		711 slas do unt			Qmi			
Ardi-4		iff stas do not		<u>.</u>	G201-31	,		
Office	}	fit- Scrap Jestmay				\sim		
(3)		Der Sprage Byll				·		
		700000						
		/	-	440			*	227
				4		393		
		*				A	j.	
							ā,	
		•		-2			:	!
			- 4					

NOTE: Date & initial all entries

윾

X



NOT TO SCALE

DOCUMENT

ᇝ

- F

₹

PURPOSE


유

COPIED

11.01

AS

m



D3562-041 LH STEP ASSEMBLY (SHOWN)

- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 2) WELD PER DART QSI 004 UNLESS OTHERWISE NOTED
 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 POWDER COAT ENTIRE ASSEMBLY GLOSS WHITE (4.3.5.1) OR GREY SANDTEX (4.3.5.6) OR BLACK SANDTEX (4.3.5.7) OR GREEN SANDTEX (4.3.5.8) PER DART QSI 005 4.3 BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) ALL DIMENSIONS ARE IN INCHES